



**US Army Corps
of Engineers®**

Detroit District
P.O. Box 1027
Detroit, MI 48231-1027
(313) 226-6797
FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L06-26

Date: 15 JUNE 2006

Waterway: LAKE HURON

Location: MICHIGAN

CELRE-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL PORT SANILAC HARBOR

1. Surveys performed within the Federal navigation channel at Port Sanilac Harbor, Michigan during June 2006, indicate shoaling as shown on the back of this sheet.
2. Mariners are urged to use extreme caution in the area.
3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L06-26. Internet address: <http://www.lre.usace.army.mil> Go to: Detroit Home Page, Who We Are, Operations Office Home Page.

DONALD P. LAUZON
Lieutenant Colonel, U.S. Army
District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2006.



The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.

Surveys taken: **June 2006**

0ptsan.bmp

All soundings are in feet and are referenced to Low Water Datum elevation 577.5 ft. above Mean Sea Level IGLD, 1985.



Shoals indicate least available depth below LWD

PORT SANILAC HARBOR, MI

CONDITION OF CHANNEL

ISSUED: **19 June 2006**

U.S. Army Engineer District, Detroit